



Part Number: 258-6301

Application: FORD GODZILLA 7.3L

Cap Screw without Washer - Rod Bolt

Installation

- [1] Please check the part-number(s) for your application against the part-number(s) listed on the instruction sheet.
- [2] Make sure there is an adequate chamfer around the bolt hole on the connecting rod cap to clear the radius under the head of the bolt.
- [3] Lubricate the threads and the under head of the bolt with ARP Ultra-Torque Fastener Assembly Lubricant.
- [4] ARP recommends using the **STRETCH METHOD** when tightening rod bolts. Following the instructions for using a stretch gauge, **Stretch the bolts to .0065" - .007"**
- [5] If you do not have a stretch gauge, torque the bolts to:
40 ft-lbs
- [6] The connecting rods should always be re-sized after new rod bolts are installed.
- [7] A log should be kept on the original non-torqued length of each bolt. Bolts that have any permanent deformation or have increased in non-torqued length by more than .001 in. should be replaced.

If you have any questions or need additional information, please contact us at (805) 339-2200 or by FAX at (805) 650-0742

Automotive Racing Products

1863 Eastman Ave. Ventura, Ca 93003

www.arp-bolts.com